

Monitoring Data Record

Project Title: Twin Oaks (R-2302) COE Action ID: 199920857
Stream Name: Perennial stream flowing into the New River DWQ Number: 990491
City, County and other Location Information: Sta. 39+50 – 48+50 on US 21 S of Twin Oaks
Date Construction Completed: N/A Monitoring Year: (1) of 1
Ecoregion: _____ 8 digit HUC unit 05050001
USGS Quad Name and Coordinates: _____

Rosgen Classification: _____

Length of Project: 1334' Urban or Rural: Rural Watershed Size: _____
Monitoring DATA collected by: K. Smith, J. Wait, M. Green Date: 12/8/03

Applicant Information:

Name: NCDOT Roadside Environmental Unit
Address: 1 S Wilmington St. Raleigh, NC 27611
Telephone Number: (919) 733-2920 Email address: _____

Consultant Information:

Name: _____
Address: _____
Telephone Number: _____ Email address: _____

Project Status: Complete

Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.): Level 1 ~~2~~ ~~3~~

Monitoring Level 1 requires completion of *Section 1, Section 2 and Section 3*

Permit States: NCDOT shall visually monitor the vegetative plantings and insure complete stabilization of the stream. This monitoring shall include visual monitoring of planted vegetation quarterly for a minimum of one year after final planting.

Section 1. PHOTO REFERENCE SITES

(Monitoring at all levels must complete this section)

Attach site map showing the location and angle of all reference photos with a site designation (name, number, letter, etc.) assigned to each reference photo location. Photos should be provided for all structures and cross section locations, should show both banks and include an upstream and downstream view. Photos taken to document physical stability should be taken in winter. Photos taken to document vegetation should be taken in summer (at representative locations). Attach photos and a description of each reference photo or location. We recommend the use of a photo identification board in each photo to identify location.

Total number of reference photo locations at this site: 4 reference points, 2 photos at each

Dates reference photos have been taken at this site: 12/08/03

Individual from whom additional photos can be obtained (name, address, phone): _____

Other Information relative to site photo reference: Photo 9 documents a washed out area.

If required to complete Level 3 monitoring only stop here; otherwise, complete section 2.

Section 2. PLANT SURVIVAL

Attach plan sheet indicating reference photos.

Identify specific problem areas (missing, stressed, damaged or dead plantings):

Estimated causes, and proposed/required remedial action: _____

ADDITIONAL COMMENTS: _____ Vegetation is dormant. Snow on the ground. Dogwood and sweetgum noted; approx. 2' in height.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

The stream is very stable and is doing well. One washed out area on the south side of the upper portion of the stream (Photo 9). Difficult to assess the extent of the erosion due to the snow. Silt fence in need of repair.

Date Inspected	Station Number				
Structure Type					
Is water piping through or around structure?					
Head cut or down cut present?					
Bank or scour erosion present?					
Other problems noted?					

NOTE: Attach separate narrative sheets to each monitoring report describing/discussing the overall monitoring results. Include the identification of specific problem areas/channel failures, estimated cause and proposed/required remedial action. This should include a brief discussion of any parameter that has changed significantly from as-built.

Twin Oaks



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6

1st Quarter – December 2003

Twin Oaks



Photo 7



Photo 8



Photo 9